

TRAK[®] MACHINE TOOLS



SOUTHWESTERN INDUSTRIES, INC.

January 3, 2022

White Paper

Machining Left Hand OD and ID Threads

Procedure for all ProtoTRAK Lathes

Steps for machining left-hand O.D. threads:

1. Mount tool: You can use either an O.D. or I.D. threading tool. Mount the tool to approach the backside of the part—facing you. See Figure 1 for a photo of an O.D. tool mount.
2. ProtoTRAK Tool Setup: Go to SET-UP, TOOL SETUP. Select THREAD **OD** even if you're using an I.D. tool. Touch off the tool, and enter a **negative** number for "X."
3. Program Event: Since the threads will be machined from the backside of the part, enter **negative** numbers for all "X Begin" and all "X END." Extra position events might be necessary before and after the thread event so that the machine can safely position around the part. See Figure 2 for an example of a left-hand O.D. threading event.
4. Run: Go to RUN mode, and run the program with the spindle in reverse (REV).




Figure 1, O.D. Tool Mount

EVENT 0		EVENT 1		THREAD	
PROGRAM NAME	0	X BEGIN	-1.0000	abs	
EVENT COMMENTS	NO	Z BEGIN	0.0000	abs	
		X END	-1.0000	abs	
		Z END	-0.7500	abs	
		PITCH	0.1000		
		# PASSES	8		
		# OF SPRING PASSES	0		
		PLUNGE ANGLE	29.5000		
		SIDE	OUTSIDE		
		# OF STARTS	1		
		RPM	500.00		
		TOOL #	1		

PITCH: 0.1000

F1	F2	F3	F4	F5	F6	F7	F8
PAGE FWD	PAGE BACK	DATA FWD	DATA BACK	DATA BOTTOM	INSERT EVENT	DELETE EVENT	

Figure 2, Left-hand O.D. Threading Event

Steps for machining left-hand I.D. threads:

1. Mount tool: You **must** use a tool that's designed for left-hand I.D. threading (see Figure 3). Mount this tool to approach the backside of the part—facing away from you.
2. ProtoTRAK Tool Setup: Go to SET-UP, TOOL SETUP. Touch off the tool, and enter a **negative** number for "X."
3. Program Event: Since the threads will be machined from the backside of the part, enter **negative** numbers for all "X Begin" and all "X END." Extra position events might be necessary before and after the thread event so that the machine can safely position around the part. See Figure 4 for an example of a left-hand I.D. threading event.
4. Run: Go to RUN mode, and run the program with the spindle in reverse (REV).




Figure 3

EVENT 0		EVENT 1		THREAD			
PROGRAM NAME	0	X BEGIN	-1.0000	abs			
EVENT COMMENTS	NO	Z BEGIN	0.0000	abs			
		X END	-1.0000	abs			
		Z END	-0.7500	abs			
		PITCH	0.1000				
		# PASSES	8				
		# OF SPRING PASSES	0				
		PLUNGE ANGLE	29.5000				
		SIDE	INSIDE				
		# OF STARTS	1				
		RPM	500.00				
		TOOL #	1				
		PITCH : 0.1000					
F1	F2	F3	F4	F5	F6	F7	F8
PAGE FWD	PAGE BACK	DATA FWD	DATA BACK	DATA BOTTOM	INSERT EVENT	DELETE EVENT	

Figure 4, Left-hand I.D. Threading Event

©2006 Southwestern Industries Incorporated. All rights reserved.
 The information contained in this document represents the current view of Southwestern Industries, Inc., on the issues discussed as of the date of publication. Because Southwestern Industries must respond to changing market conditions, it should not be interpreted to be a commitment on the part of Southwestern Industries, and Southwestern Industries cannot guarantee the accuracy of any information presented after the date of publication.

This White Paper is for informational purposes only. SOUTHWESTERN INDUSTRIES MAKES NO WARRANTIES, EXPRESS OR IMPLIED, IN THIS DOCUMENT. WP072106