



SOUTHWESTERN INDUSTRIES, INC.
2615 Homestead Place, Rancho Dominguez, California 90220

<i>phone</i>	310.608.4422
<i>fax</i>	310.764.2668
<i>service</i>	800.367.3165
<i>web</i>	http://www.southwesternindustries.com

Parts Support Policy

- SWI supports all its products for as long as the components are reasonably available.
- Many electronic components are eligible for exchange. See the service price list.
- All exchanges and repairs must have an RMA number issued by the SWI Service Department.
- An evaluation fee of \$150 is applied to units sent in for repair. If repair is not authorized, this fee is still charged (even if the unit is exchanged).
- Both repaired and exchange units have a warranty of 90 days.